

NUMBER: 13

DATE: January 10, 1996

APPLICATION SERVICE

SUBJECT: EPC 100 Air Fuel Ratio Controller used with Regulators with external feedback tubes.

When installing the EPC-100 beware of Fuel Pressure Regulators with external feedback tubes (some Fisher 99's). If the Altronic control valve (stepper valve) is improperly installed inside the regulator control loop the regulator will cancel out all effects of the control valve, and it will seem the control valve is not functioning. The fuel pipe between the control valve and the carburetor should have no lines or tubes returning back to the regulator.

